

# Technical Support Notification

## Allied Electronics with BIR DIM Applications

### ► Veeder-Root Dispenser Interface Protocol over TCP/DIM (TDIM)

TLS-450PLUS consoles with Business Inventory Reconciliation (**BIR**) require the use of a Dispenser Interface Module (**DIM**). The DIM allows the console to receive transaction data from a Point-of-Sale (**POS**) system.

On the TLS-450PLUS console, the built in TCP/IP (ethernet) port can be utilized as a TCP/IP DIM (**TDIM**). In addition to allowing remote capabilities, the TCP/IP port will also transfer BIR data.

**Note:** Only ETH1 can be programmed as a TDIM. This is the ethernet port closest to the front of the console.

The following instructions explain how to connect the TDIM to an Allied NeXGen or AEGIS.

### ► Enabling TDIM Capabilities with Allied



1. The default serial port on NeXGen/AEGIS is COM2. This will need to be unassigned via the DGS application (set to Not in Use). It will look like this in the NeXGen.INI file: COM2=NON
2. Also, in the NeXGen.ini file, you will need to include these entries:

```
[TCP_LOGGING]
FIM=True
```

```
[TANK_GAUGE]
IpAddress=x.x.x.x (where x.x.x.x = IP of the TLS-450PLUS)
TcpPort=35555 (Default on TLS-450PLUS TDIM port)
```

► **TDIM and Allied Interface – TLS-450PLUS Setup**  
Programming

How to enable TDIM capabilities with a TLS-450PLUS console:

Menu → Setup → Communication → TDIM Port

- ❑ **Configured:** Enabled
- ❑ **Label:** Example: TDIM or POS
- ❑ **Port Number:** 35555
- ❑ **Protocol:** VRProtocolDIM
- ❑ **Units Reports:** Default is set to US

Setup > Communication > TDIM Port

ID 16

Configured  Enabled  Disabled

Label TDIM

Port Number 35555

Protocol VRProtocolDIM

Units Reported US

Home

Favorites


Menu

Actions

1 TDIM (Eth 1)



► **TDIM and Allied Interface – TLS-450PLUS Setup (Continued)**  
Wiring Configurations



Ensure both the TLS-450PLUS and NeXGen are on the same subnet. Assigned ports in both the TLS-450PLUS and Allied must match, as shown on the first page of this notice.

► **Further Information**

- Contact Veeder-Root Technical Support at 1.800.323.1799 for additional help or questions.
- Learn more about [BIR](#) on our website.